



Photogenica Laser Post Treatment Skin Care Instructions

You have been treated with the Cynosure PhotoGenica laser. The treated area is delicate and should be treated gently. Immediately following treatment, the area will show possible bruising with some swelling. Blistering may occur. To prevent any complications, please follow these instructions:

- Do not rub, scratch, or pick the treated area. If a crust develops apply a thin layer of antibiotic ointment to the treated area several times a day to keep the area moist.
- Do not shave for one to three days if blistering and or crusting occurs.
- Avoid exposure to the sun. Apply sunscreen with a SPF 30 or greater to the area whenever exposure to the sun is unavoidable.
- Avoid exercises that can cause vasodilatation for one week post treatment. Walking is encouraged.
- If makeup is allowed, it must be applied and removed delicately to the treated area.
- Please contact the office immediately if the treated area becomes tender and shows signs of infection (pus.)